

Safety Measures in Welding and Spray Painting in Pakistan: A Systematic Review

by Adnan Fazal Manzoor

| | | | |
|----------------|---|-----------------|-------|
| FILE | ADNAN_FAZAL_MANZOOR_PAPER_ON_SAFETY.DOCX (76.45K) | | |
| TIME SUBMITTED | 22-JUL-2020 10:03AM (UTC+0500) | WORD COUNT | 3439 |
| SUBMISSION ID | 1360691528 | CHARACTER COUNT | 19043 |

Safety Measures in Welding and Spray Painting in Pakistan: A Systematic Review

Adnan Fazal Manzoor, B.E (Chem), MS¹, Dr. Asad Ullah, B.E (Chem), PhD², Shahid Munir Bhatti, B.E (Chem)

Department of Management Sciences ¹

Comsats University, Pakistan

Baluchistan University of IT & Management Sciences ²

Quetta, Pakistan

Correspondence Author: Adnan Fazal Manzoor

Correspondence email: chemengg1980@gmail.com

Funding N/A

Conflict of interest N/A

Table 01

Fig 01

Safety Measures in Welding and Spray Painting in Pakistan: A Systematic Review

Abstract

Use of Personnel Protective Equipment (PPE) is an integral segment in occupational safety program in order to improve injury and loss prevention; however, in developing nations the occupational safety is often undermined. Across the under developed countries, employees in informal sector are executing their duty in the absence of adequate safety setup. We conducted a Systematic literature review of studies on use and impact of protection equipment in informal sector (Welding and Spray Painting) of Pakistan. Google Scholar was searched for use of occupational personal safety studies conducted in English in two sectors (Welding and Spray Painting) in Pakistan. Search resulted in fifty six (56) studies. The initial, abstract and full text review finally yielded seven (7) studies for this review. Overall state of use of PPE was found very disappointing. No Policy exists and poor field implementation was reported. Eye Shields and gloves were among the highest available used PPEs. There was no use of respirators in welding and spray painting areas. This is the first-ever review on the state of occupational safety in informal sector (welding and spray painting) of Pakistan. Detailed studies in informal sector are required to depict the safety practices.

Keywords Worker Health, PPE, Accident, Injury, Training, Occupational Safety

Introduction

With the advancement of entrepreneurship and commercial activities, more and more small business are setting place in the informal sector. Especially the welding and spray painting are part of many commercial, manufacturing and construction-related activities (Anderson & Kovach, 2014). It is believed that approximately 1 million people around the globe are engaged in welding and spray painting jobs and there will be around 26 % increase in demand in 2020.

Occupational workers in these areas are prone to many injuries and risk while at work, especially in the absence of proper occupational health and safety (OHS) setups (Ghimire, Budhathoki, Niraula, Shrestha, & Pokharel, 2018). The Occupational ill health and injury caused by welding and Spray painting included but not limited to asthma (Temel et al., 2010), respiratory tract problems (Hammond et al., 2005; Rana et al., 2019), Bronchitis (Kaukiainen, Martikainen, Riala, Reijula, & Tammilehto, 2008) metal fumes toxicity (Bakri, Hariri, & Ismail, 2019) and eye injuries (Isah & Okojie, 2006). The occupational risks include explosion, fire, burns etc. Eye injuries account 25 percent for welding claims (Adewoye, Awoyemi, Ibirongbe, Babatunde, & Ibrahim, 2013).

To mitigate the hazardous effects of welding and paint fumes, the best approach is to manage the threat by applying the hierarchy of controls i.e. elimination, substitution, administrative controls, engineering, and environmental controls and by the use of PPE (Jawaid, 2018). Elimination or Substitution of threat and application of Engineering and environmental controls is an advisable and viable approach, however, due to limited resources and costly technology, it is not always possible in countries like Pakistan to substitute and switch over to safer technology. Companies require the services of a qualified safety specialist to ascertain which course of action is most suitable in any given situation (Korczynski, 2000). Viable options available in under developed countries are administrative controls and the use of PPE. Administrative controls comprise issuances of standard procedures and protocols, rotations of employees and awareness programs.

PPEs are considered an essential necessity in order to mitigate the effects of any accident and saving the life and health of workers from toxic effects of welding and painting fumes. The

selection of appropriate level of PPE depends upon the toxic gas level at site (Leman, Omar, & Yusof, 2010).

Previous studies revealed a state of poor knowledge about health hazards associated with welding and spray painting fumes (Adewoye et al., 2013). Moreover, there are also evidences that despite awareness of the health hazards, there is reluctance in use of PPE among occupational workers (Budhathoki, Singh, Sagtani, Niraula, & Pokharel, 2014). The injuries and risks caused by welding and paintings hazards are 100 % preventable if proper PPE is donned (Korczynski, 2000). The main components of PPE for welding and spray painting tasks are helmet, eye shield, respirator, gloves, and safety boots (Alferez, 2017; DeKeuster & Stowell, 2016; Garcia, 2018; Keer, McLean, Glass, & Douwes, 2018; Matthews et al., 2015). The helmet fitted with eye shield is used extensively for protection of eyes. To protect the hands from conventional injury and shock gloves are used. To get protection from fumes of welding and spray painting, use of respiratory protection is inevitable (Methner & Page, 2017; Pronk et al., 2007; ROSENBERG & Tuomi, 1984).

With the advancement in technology, there is a continuous up gradation in the field of PPE both in terms of design and material in welding and spray technology. Most studies were conducted in developed countries, whereas limited research has been conducted in under developed countries. Welders and spray painters in Pakistan have mere arrangements of safety protection at work. The working conditions are poor and occupational workers health surveillance system is weak (Kamal, Malik, Fatima, & Rashid, 2012). The aim of this study was to ascertain the use of safety measures in welders and spray painters in Pakistan.

Method

Study Design

A systematic literature review (SLR) was done using PRISMA guidelines.

Search Strategy

Studies were searched through Google Scholar and DOAJ using specific words. Following specific words were used: 'PPE', 'protection Equipment', 'eye shield', 'face mask', 'respirator', 'gloves', 'welding', 'Spray Painting', 'Fumes fever', 'Pakistan', 'Punjab', 'Sindh', 'Baluchistan' and

‘Khyber Pakhtunkhaw’. The studies were included till 2019 with a limit of 10 results per page. First five pages for each key word were reviewed. After initial scrutinizing, the authors conducted review of title and abstracts for final selection of studies for comprehensive review.

Selection of Studies

Occupational surveys, Exploratory and descriptive studies conducted in any city of Pakistan and published in English language were incorporated in review. The review emphasised on the use of protective equipment in welding & sprays painting industry. Therefore only those studies are included in which PPE is discussed. Conference papers were excluded.




Fig No 1 Flow chart of Literature Survey

Results

Types of studies

After thorough scrutinizing and abstract review, a total thirty two (32) studies were selected for full study review out of fifty six (56) studies. Full study review yielded seven (7) relevant studies which are included in this study and displayed in Table No 1. We reported safety issues in

occupational welding / spray painting studies in Pakistan. Total seven studies discussed the use of PPE in welding & spray painting and effects on human health. Three of them discussed welding in shops and manufacturing areas (Hassan, Nasir, Anwar, & Talib, 2017; M. Shaikh, 2001; T. Q. Shaikh & Bhojani, 1991), while one study discussed the effects on lungs (Meo, Azeem, & Subhan, 2003). Three studies discussed the health effects of spray painting on painters and machinists in the absence of PPE (Kamal & Malik, 2012; Kamal, Qayyum, Cheema, & Rashid, 2011; Kamal & Rashid, 2014).

| Author/study year | Study design | Participants | Area Focused | Main Findings |
|------------------------|-------------------------------|--|---|--|
| (Hassan et al., 2017) | cross sectional descriptive | 70 welders | Eye, Burns and injury | Poor awareness and education in welding profession Lack of standardized eye shielding Poor Health and injury support |
| (Kamal & Rashid, 2014) | Cross sectional study | 20 mechanics, 20 painters 20 control | Blood samples | Painters are more prone to Benzene exposure Poor ventilation system, poor PPE and hygiene state and uncontrolled use of chemicals |
| (Kamal & Malik, 2012) | Survey and Experimental Study | 29 Painters 25 Mechanists 20 Control | Hematological evidence to exposure to chemicals | Awareness about use of PPE is to be enhanced |

| | | | | |
|--------------------------------|--------------------------------------|---|---|---|
| (Kamal et al., 2011) | Experimental Study | 20 Painters 20 Mechanists 20 Control sample | Evaluate the blood naphthalene levels (NAPH) evaluate blood naphthalene | Poor work place Hygiene and long exposure are major factor of exposure. Smoking and non adherence to PPE are major personal factors. |
| (Meo et al., 2003) | Matched case control cross sectional | 50 non smoker welders | Lungs, Respiratory area | Welders showed a positive indication of lungs disease in the absence of PPE |
| (M. Shaikh, 2001) | Cross Sectional Survey | 208 welders | | Lack of awareness and relevant education |
| (T. Q. Shaikh & Bhojani, 1991) | Cross Sectional Descriptive | 36 welders | Eye injuries, Burns | Poor education & awareness No use of protective equipment They rate the occupation hazardous / nonhazardous based on their experience |

Table No 1

Safety Culture, Awareness and Education

There is a dire deficiency of safety culture in welding and spray painting areas in Pakistan. Workers were executing their jobs without formal training and education, they were unaware of the majority of hazards associated with welding & spray painting (Hassan et al., 2017; T. Q. Shaikh & Bhojani, 1991). There were no safety policies and operating instructions for occupational workers in those areas. Workers were getting training through observation and experiences without any written instructions and formal training (Hassan et al., 2017; T. Q. Shaikh & Bhojani, 1991). There were no statistical data available about the exact number of welders and spray painters working in the country; in addition no independent legislation was formulated for occupational workers working in informal sector in Pakistan (Hassan et al., 2017). The absence of statistical data regarding occupational welders and spray painters in informal sector was considered a major constraint to devise an effective OHS policy (Hassan et al., 2017; T. Q. Shaikh & Bhojani, 1991).

Availability and USE of PPE

Studies showed that workers were not issued proper PPE to prevent the occupational injury (T. Q. Shaikh & Bhojani, 1991), moreover, in certain cases the PPE issued were not standardized and appropriate for injury prevention (Hassan et al., 2017). One study pointed towards the positive result of lungs disease in the absence of PPE (Meo et al., 2003). Studies pointed out the tendency of workers for not using the PPE (Kamal et al., 2011), one study highlighted the significance of PPE for injury and ill health prevention (Kamal & Malik, 2012). One study explained that workers were considering injuries as part of job and they were not using PPEs (Hassan et al., 2017). Gloves were reported on the top of list in available PPEs, where as eye shields and respirators were reported on 2nd and 3rd place (Hassan et al., 2017).

Medical Support and Reporting Mechanism

Studies revealed no proper medical support was available to occupational welders and spray painters in Pakistan. In addition, there was no first aid equipment available and there was no first aid training provided to those workers (Hassan et al., 2017). Poor industrial hygiene and extended working duration in contaminated environment were also considered as contributing factors in workers ill health (Kamal et al., 2011). Studies pointed out that there was no Reporting and Investigation mechanism of accidents in informal sector of Pakistan, which was a major impediment in executing the corrective actions (M. Shaikh, 2001).

Discussion

We conducted review on physical protection measures and effects on workers health in case of non availability of these measures in welding and spray painting (informal sector) of Pakistan. There is deficiency of quality studies in these disciplines and advanced studies should be conducted to ascertain the impact of safety practices in welding and spray painting in Pakistan. The major issues observed were absence of safety culture at work place, unawareness and lack of education about hazards and their impacts, non availability of operating procedures, non availability of PPEs, sub standards PPEs and tendency to work without wearing proper PPEs. There is a need to nourish the safety culture at work stations and proper awareness and education about safe work practices be fostered among the workers. The awareness about hazards and cost of PPE are major factors while deciding about use of safety measures in Pakistan (Hassan et al., 2017).

Risk assessment and awareness about hazards is the first step in order to motivate the workers to adopt any safety program and adopt safe measures. Workers should know the result of exposing themselves to these hazards. Studies showed that this most important step is entirely missing in Pakistan's informal sector. The awareness level was found very poor; no proper education was imparted to workers to operate safely (M. Shaikh, 2001). The occupational workers in these professions are normal workers with education less than high school and majority of them work on daily wages. There is no proper OHS training system for these workers. Workers should be trained to execute their assigned jobs in a safe manner (Hassan et al., 2017; M. Shaikh, 2001).

This study also high lights the non availability or availability of sub standard PPE at work stations in Pakistan. PPEs come as a last resort to prevent injury if other engineering and administrative measures fail. Studies revealed that in Pakistan other measures are also not in place as well. The most widely used PPEs are gloves and eye shield. The standardization of PPE is another challenging domain as workers were using normal eye shields instead of certified equipment (Hassan et al., 2017). The appropriate training should be provided to the workers to use PPE effectively (Kamal & Malik, 2012). The most alarming fact was that workers are using available protection measures for acute effects only e.g. protection from plasma, heat and physical effects only whereas chronic effects in terms of inhalation of contaminated air / welding fumes were not considered by workers in those areas (Jafari & Assari, 2004).

Studies also showed the adverse effects of workers health in those areas mainly due to non availability of PPE or non adherence to standardized protection measures. Different studies showed the effect on workers health systems which include lungs, blood, eyes etc (Kamal et al., 2011; Meo et al., 2003). In continuation to adverse effects, this study also highlights that there were no medical support available to workers. There was no concept of first aid at site, in addition, no annual or routine medical assessment support was available to the occupational workers in welding and spray painting of informal sector of Pakistan (Hassan et al., 2017). The study also showed that there was no mechanism of incident or accident reporting in welding and sprays painting of informal sector of Pakistan. Due to non reporting mechanism, there is no visibility at policy level about the real time problems and state of OHS at ground level. Moreover no corrective or preventive measures can be suggested by policy level to the occupational workers due to non reporting mechanism.

This study has only considers the Google scholar and DOAJ in search. Other data bases may yield more elaborated results.

Conclusion The state of OHS in welding and spray painting in informal sector of Pakistan depends upon many contributing factors. Mainly the unawareness and lack of education were major factors along with non availability of PPEs. Due to poor regulatory implementation of OHS laws, the overall state is very disappointing. Extensive Training and proper education can enhance the safety state of occupational workers in these areas. Vocational training institutes can play significant role in promoting safe working culture. Studies involving many under developed countries are required to report the awareness level and use of safety measures by welders and spray painters in informal sector.

Disclosure statement. No potential conflict of interest was reported by the authors.

Adewoye, K. R., Awoyemi, A. O., Ibirongbe, D. O., Babatunde, O. A., & Ibrahim, T. (2013). Knowledge on the health effects of welding smoke, use of ppe among electric-arc welders in ilorin south, north central Nigeria. *Journal of Asian Scientific Research*, 3(9), 924-932.

Alferez, M. (2017). Welding finger cot and hand guard: Google Patents.

Anderson, N. C., & Kovach, J. V. (2014). Reducing welding defects in turnaround projects: A lean six sigma case study. *Quality Engineering*, 26(2), 168-181.

Bakri, S., Hariri, A., & Ismail, M. (2019). *Metal fumes toxicity and its association with lung health problems among welders in automotive industry*. Paper presented at the Journal of Physics: Conference Series.

- Budhathoki, S. S., Singh, S. B., Sagtani, R. A., Niraula, S. R., & Pokharel, P. K. (2014). Awareness of occupational hazards and use of safety measures among welders: a cross-sectional study from eastern Nepal. *BMJ open*, 4(6), e004646.
- DeKeuster, M. T., & Stowell, R. M. (2016). Auto-Darkening Welding Helmet: Google Patents.
- Garcia, A. N. (2018). Helmet with eye protection: Google Patents.
- Ghimire, A., Budhathoki, S. S., Niraula, S. R., Shrestha, A., & Pokharel, P. K. (2018). Work-related Injury among Welders Working in Metal Workshops of Dharan Municipality, Nepal. *Journal of Nepal Health Research Council*, 16(2), 156-159.
- Hammond, S. K., Gold, E., Baker, R., Quinlan, P., Smith, W., Pandya, R., & Balmes, J. (2005). Respiratory health effects related to occupational spray painting and welding. *Journal of occupational and environmental medicine*, 47(7), 728-739.
- Hassan, S. M., Nasir, U., Anwar, K., & Talib, U. (2017). An assessment of the level of awareness and reported complaints regarding occupational health hazards and the utilization of personal protective equipments among the welders of Lahore, Pakistan. *International journal of occupational and environmental health*, 23(2), 98-109.
- Isah, E., & Okojie, O. (2006). Occupational health problems of welders in Benin City, Nigeria. *Journal of Medicine and Biomedical Research*, 5(1), 64-69.
- Jafari, A. J., & Assari, M. J. (2004). Respiratory effects from work-related exposure to welding fumes in Hamadan, Iran. *Archives of Environmental Health: An International Journal*, 59(3), 116-120.
- Jawaid, A. (2018). Dealing with Welding Fumes. *Tech Directions*, 77(6), 17-18.
- Kamal, A. & Malik, R. N. (2012). Hematological evidence of occupational exposure to chemicals and other factors among auto-repair workers in Rawalpindi, Pakistan. *Osong public health and research perspectives*, 3(4), 229-238.
- Kamal, A., Malik, R. N., Fatima, N., & Rashid, A. (2012). Chemical exposure in occupational settings and related health risks: a neglected area of research in Pakistan. *Environmental toxicology and pharmacology*, 34(1), 46-58.
- Kamal, A., Qayyum, M., Cheema, I. U., & Rashid, A. (2011). Biological monitoring of blood naphthalene levels as a marker of occupational exposure to PAHs among auto-mechanics and spray painters in Rawalpindi. *BMC Public Health*, 11(1), 467.
- Kamal, A. & Rashid, A. (2014). Benzene exposure among auto-repair workers from workplace ambience: A pioneer study from Pakistan. *International journal of occupational medicine and environmental health*, 27(5), 830-839.
- Kaukianen, A., Martikainen, R., Riala, R., Reijula, K., & Tammilehto, L. (2008). Work tasks, chemical exposure and respiratory health in construction painting. *American journal of industrial medicine*, 51(1), 1-8.
- Keer, S., McLean, D., Glass, B., & Douwes, J. (2018). Effects of personal protective equipment use and good workplace hygiene on symptoms of neurotoxicity in solvent-exposed vehicle spray painters. *Annals of work exposures and health*, 62(3), 307-320.
- Korczynski, R. (2000). Occupational health concerns in the welding industry. *Applied occupational and environmental hygiene*, 15(12), 936-945.
- Leman, A., Omar, A., & Yusof, M. (2010). Monitoring of welding work environment in small and medium industries (SMIs). *Int J Res Rev Appl Sci*, 5, 18-26.
- Matthews, W. T., Harris, J. A., Lynch III, J. D., Mariano, D. A., Colburn, E. R., & Aby-Eva, G. (2015). User-friendly welding helmet assembly: Google Patents.
- Meo, S. A., Azeem, M. A., & Subhan, M. (2003). Lung function in Pakistani welding workers. *Journal of occupational and environmental medicine*, 45(10), 1068-1073.
- Methner, M. M., & Page, C. (2017). Evaluation of exposure to crystalline silica, welding fume, and isocyanates during water heater manufacturing: NIOSH HHE report.

- Pronk, A., Preller, L., Raulf-Heimsoth, M., Jonkers, I. C., Lammers, J.-W., Wouters, I. M., . . . Heederik, D. (2007). Respiratory symptoms, sensitization, and exposure–response relationships in spray painters exposed to isocyanates. *American journal of respiratory and critical care medicine*, 176(11), 1090-1097.
- Rana, H. 5., Akhtar, M. R., Islam, M. B., Ahmed, M. B., Lio, P., Quinn, J. M., . . . Moni, M. A. (2019). Genetic effects of welding fumes on the development of respiratory system diseases. *Computers in Biology and Medicine*.
- ROSENBERG, C., & Tuomi, T. (1984). Airborne isocyanates in polyurethane spray painting: determination and respirator efficiency. *American Industrial Hygiene Association Journal*, 45(2), 117-121.
- Shaikh, M. (2001). Hazard perception and occupational injuries in the welders and lathe machine operators of Rawalpindi and Islamabad. *Journal-Pakistan Medical Association*, 51(2), 71-73.
- Shaikh, T. Q., & Bhojani, F. A. (1991). Occupational injuries and perception of hazards among road-side welding workers. *J Pak Med Assoc*, 41(8), 187-188.
- Temel, O., Sakar Coskun, A., Yaman, N., Sarioglu, N., Alkac, C., Konyar, I., . . . Keskin, E. (2010). Occupational asthma in welders and painters. *Tuberk Toraks*, 58(1), 64-70.

Safety Measures in Welding and Spray Painting in Pakistan: A Systematic Review

ORIGINALITY REPORT

%**4**

SIMILARITY INDEX

%**4**

INTERNET SOURCES

%**3**

PUBLICATIONS

%**4**

STUDENT PAPERS

PRIMARY SOURCES

1

ns-proxy1.massey.ac.nz

Internet Source

%**1**

2

www.sci-int.com

Internet Source

%**1**

3

Submitted to Texas A&M University, Health
Science Center

Student Paper

%**1**

4

www.uaar.edu.pk

Internet Source

%**1**

5

web-tools.uts.edu.au

Internet Source

%**1**

6

journals.sagepub.com

Internet Source

%**1**

EXCLUDE QUOTES ON

EXCLUDE
BIBLIOGRAPHY ON

EXCLUDE MATCHES < 15
WORDS